



- [illegible]

- Miscellaneous Legend**
- Denotes location of S&P.
 - Denotes location of Floor Slip.
 - Denotes New 1160m Floor.
 - Indicates location of FD305
 - Indicates location of FD305 SE
 - Indicates location of FD305 fire
 - Vision Panel In Door
 - Fire gully protection (Vibration)
 - Heart Detector
 - Smoke Detector to BSS5593
 - Optical Smoke Detector
 - MMRH / Butler lift exit point
 - Surface mounted from "tongue and groove" joining light and glass panels. The installation was approved by the client's representative and approved by all attendees at the meeting.
- EMERGENCY SIGNAGE TO BE INSTALLED**
- EXIT
 - FIRE EXTINGUISHER (FIRE STOP)
 - Flashing beacon linked to area detection in Reception Unit
 - Washing Machine & Dryer
 - No Smoking within 30 metres prohibited walking

CONSTRUCT

C5	07.10.22	Provision as decided in Building Contract completion
C4	29.06.22	Balcany edges revised
C3	29.11.21	General revisions
C2	28.03.21	Wall type references to drawings added
C1	22.09.21	Construction issues
T2	05.08.21	General revisions
T1	02.07.21	Tender issues
Rev	Date	Revised

John Farquharson P
 6-Taro Hall Lane,
 Gidara Park,
 Essex, RM2 6BD
 Tel: 02075 75 01 11

John Farquharson P
6 Marc Hall Lane,
Gidea Park,
Essex, RM2 6HD
Tel: 0208 75 00 11